



**evektor** australia

Evektor Australia PO Box 237, Black Rock, Victoria 3193, Australia  
Tel & fax +61 (0) 3 9592 3101 Mobile +61 (0) 413 900 892

[www.evektor.com.au](http://www.evektor.com.au)

## **APPROVED OWNER/PILOT MAINTENANCE ACTIVITIES ON VH- AIRCRAFT**

*The following activities, which do not involve the dismantling of or interference with any structure, operating system or the use of specialised tooling, comprise approved pilot maintenance:*

1. Removal and installation of landing gear wheels, tyres and repair of pneumatic tubes.
2. Servicing of landing gear wheel bearings, such as cleaning and greasing.
3. Replacement of defective safety wiring or split pins, excluding those in control systems.
4. Any lubrication not requiring disassembly other than removal of non-structural cover plates, cowlings and fairings.
5. The making of simple fabric repairs not including lacing or rib stitching or the removal of structural parts or control surfaces.
6. Replenishment of hydraulic fluid in hydraulic reservoirs.
7. Repairs to upholstery and decorative furnishings of the cabin or cockpit interior.
8. Replacement of side windows in unpressurised aircraft.
9. Replacement of seats when it does not involve disassembly of any primary structure and is subject to the approved loading system.
10. Replacement of seat belts and harnesses.
11. Replacement of bulbs, reflectors, glasses, lenses or lights.
12. Replacement of any cowling not requiring removal of the propeller or disconnecting of controls.
13. Replacement or cleaning of spark plugs and setting of their gaps.
14. Replacement of batteries.
15. Changing of engine oil and fuel, oil and air filters.
16. Removal and replacement of glider tow hooks.
17. Removal and replacement of role equipment used for agricultural operations.
18. Replacement of placards and markings.
19. Application of preservative or protective materials to components where no disassembly of primary structure or operating systems is involved such as seaplane preservation (paraloketone to control cables, etc.), anti-corrosive paint to structures or components where such coating is not prohibited or is contrary to good practice.
20. Removal and refitting of doors, where no disassembly of primary structure or operating system is involved, of aircraft that have a flight manual supplement that is approved for operations without that door.
21. Daily Inspections.
22. The second independent inspection of flying controls.
23. On VFR aircraft only:
  - (i) replacement of wire aerials by components of identical electrical design;
  - (ii) re-termination of radio system plugs, sockets or disconnects;
  - (iii) adjustment of contacts in microphone and headset jacks;
  - (iv) replacement of radio system switches, relays and similar minor components with identical components.

*If you are using tooling that requires calibration, it is your responsibility to ensure that the tooling is within its calibration tolerance and test period.*